DATE: SEPTEMBER 27, 2005

TO: ALL INTERESTED PARTIES

RE: M. V. HYAK

DOCKSIDE PRESERVATION

CONTRACT 00-7039

ADDENDUM NO. 2

This is to inform you of the following updates and changes to the Invitation For Bids (IFB) for the above-referenced project:

SPECIFICATIONS IFB Volume I

Attached hereto and incorporated herein are revisions to the IFB Special Provisions and the Technical Specifications documents.

QUESTIONS AND ANSWERS

Attached hereto and incorporated herein are four (4) Questions and Answers regarding the IFB Technical Specifications documents.

All other terms and conditions remain unchanged. All bidders will be required to acknowledge receipt of this Addendum on the Bid Form. All Addenda will become a part of the Contract.

Sincerely,

Barbara Olson Contracts Coordinator

Attachment

G:\PWC\VESSEL\ FY 06\7039

ATTACHMENT TO ADDENDUM NO. 2

SPECIAL PROVISIONS IFB Volume I

WSF PERSONAL FACILITIES Section 4

Page 4, lines 34 - 40. Paragraph G.

Delete the entire text in paragraph "a" and replace with the following new text:

"Counter area; sink with hot and cold running water; supply a certified non-contaminated hot and cold fresh water dispenser with a sealed five (5) gallon water bottle service to be delivered to the Coffee Mess area, estimated at one (1) per day until redelivery of the Vessel(s). A refrigerator of at least 6.0 cubic feet; a microwave oven; coffee maker; trash can; towel rack; paper towel dispenser and cabinet storage space."

VESSEL SHIPCHECKS Section 22

Page 17, line 3. Revise the sentence beginning with the words "The M.V. Hyak is", and replace with the following new text:

"The M.V. Hyak is currently at the Eagle Harbor Maintenance Facility."

TECHNICAL SPECIFICATIONS

REPLACE VEHICLE DECK STEEL Item 43

Page 70, lines 1 - 3. Paragraph C. Delete the entire text in paragraph "C" and replace with the following new text:

"Crop out and renew Upper Vehicle Deck Steel & Curtain Plate Frames in areas as defined in Paragraph E and F of this Item. Beam, Stringer and Frame to plate connections shall be continuous welded to both sides in all areas of new deck steel."

Page 70, line 16. Paragraph "F".

Revise the first phrase in Paragraph "F" to read as follows:

"Curtain Plate Frames to be replaced include:"

Page 70, line 20. Paragraph F. 3. Revise Paragraph F. 3. to read as follows:

"Subject to the provisions in Item 44, remove and reinstall vehicle deck curbing in way of work, as needed to complete the work."

QUESTIONS AND ANSWERS

1. Q. [IFB, Technical Specifications, Item No 7, Steering System Hydraulic Piping Upgrade]. Page 21. Paragraph B.

Work Item specification paragraph B directs to remove and dispose of all fluids in both steering systems. Contractor notes the Work Item Specification does not call out to replenish system with new oil. Contractor assumes ships force personnel will accomplish this using government provided oil.

- A. The Contractor shall follow the IFB Technical Specifications. Washington State Ferries (WSF) does not desire the Contractor to either provide or replenish the oil.
- **Q.** [IFB, Technical Specifications, Item No 43, Replace Vehicle Deck Steel] Page 70, paragraph C.

Paragraph C. States to crop out and renew Lower Vehicle Deck steel. The specification does not state whether to renew the underdeck beam/stringer, only to weld them continuously. There are no dimensions for renewals of the lower deck. Is it the whole deck in it's entirety?

A. Please see the revisions to the IFB Technical Specifications in this IFB Addendum.

- **Q.** [IFB, Technical Specifications, Item No 43, Replace Vehicle Deck Steel] Page 70. Paragraph E. Is foam to be replaced in areas of curb renewal in way of frame renewal?
 - A: The Contractor is to follow the IFB Technical Specifications. The Technical Specifications do not require the Contractor to re-install foam in any reinstalled curbing.
- **Q.** [IFB, Technical Specifications, Item No 43, Replace Vehicle Deck Steel] Page 70.
 - a. Paragraph F deals with Frames to be replaced.
 - b. Paragraph F. 3 states to renew curbing in way of work. Is this the same curbing as mentioned in item 44? (600 feet).
 - c. Paragraph F. 4.a thru d. states locations of upper vehicle deck and gives a total (10). Is that number of web frames to be renewed against the curtain plate from 12" under the deck to 5' above. This specification does not say to renew any decking. Is this to be the entire upper vehicle deck between the casing to the curtain at the designated frames mentioned? Are the deck stiffeners to be renewed along with the plating?
 - A. a. Please see the revisions to the IFB Technical Specifications in this IFB Addendum.
 - b. Please see the revisions to the IFB Technical Specifications in this IFB Addendum.
 - c. Please refer to the above Answer to Question 4 a.

(END)